
Personal Protective Equipment



What is Personnel Protective Equipment-PPE?

- PPE is defined as a device or clothing worn by a worker to help prevent direct exposure to hazards and protect workers from Bodily Injury
- PPE is the least preferred method of protection, and should be used following engineering and administrative controls methods.



Hierarchy of Control Measures

- 1. Engineering Controls
- 2. Administrative Controls
- 3. Personal Protective Equipment


Most Effective Control

Least Effective Control

Engineering Controls

- Engineering Controls are built into an operation and require no activation from the employee.
- Examples include selfcapping syringe needles, ventilation systems, fume hoods and substitution to a less hazardous process or

chemical.



Administrative Controls

Are changes in work practices such as supervision, schedules, and training with the goal of reducing the duration, frequency, and severity of exposure to hazardous situations

Less effective method used when engineering controls are not feasible.

Examples.....

- Examples include written operating procedures, training and limiting exposure times
- Personal hygiene
- Housekeeping and maintenance

Appropriate attire for the lab

- Always wear a lab coat in the laboratory.
- Do not wear tank-tops and shorts inside a lab.
- Tie back or secure long hair and loose clothing.
- Wear shoes that protect or cover your feet. Do not wear flipflops, sandals or perforated shoes



Mandatory minimum PPE requirement

- Protective eye wear
- Lab coat
- Long pants
- Close-toed shoes
- Chemical resistant gloves (when working with hazardous substances)


Establishing a PPE Program

- First Hazard Assessment
 - Assess the workplace to determine if hazards are present, or are likely to be present, which necessitate the use of PPE
- Once the proper PPE has been selected, training must be provided to everyone required to use PPE

Training

Employees required to use PPE must be trained to know at least the following:

- When PPE is necessary
- What type of PPE is necessary
- How to properly put on, take off, adjust, and wear
- Limitations of the PPE
- Proper care, maintenance, useful life and disposal



Users Responsibilities

- Attending training sessions on PPE
- Properly wearing the PPE
- Proper care and maintenance of the PPE
- Informing the supervisor about the need for repair and replacement

Eye Protection

Read this sign again tomorrow.



Eye Protection

Eye protection is required (but not limited to):

- When chemicals, glassware, or a heating source is being used
- When working with solid materials or equipment under stress, pressure, or force that might cause fragmentation or flying particles
- When an activity generates projectiles, or uses elastic materials under stress (e.g., springs, wires, rubber, glass), or causes collisions
- When dust or fumes are present
- When using preserved specimen

Types of eye protection

- Eye protection is mandatory in all areas where there is a potential for injury.
- The type of eye protection required depends on the hazard. For most situations safety glasses with side shields are adequate.
- Goggles or face shields are required in specific operations where there is danger from splashes of corrosive liquids or flying particles
- If a splash occurs proceed to nearest eyewash fountain and flush eyes with water from the eye outward for at least 15-30 minutes.
- Recommended that contact lenses not be worn in laboratory.

Goggles

- Usually enclose or protect the eye and the facial area immediately surrounding the eyes from impact, dust, and splashes
- Often worn when danger from splashes of corrosive liquids or flying particles





Welding Shields

Protect eyes from burns, flying sparks, metal spatter, and slag chips produced during welding, brazing, soldering, and cutting





Face Shields

- Device used to protect the entire face from flying objects, debris and chemical splashes or potentially infectious fluid.
- Do <u>not</u> protect from impact hazards





Choosing Gloves: Compatibility

Three important properties determine the type of chemical-resistant gloves worn:

- Chemical degradation Some chemicals cause gloves to deteriorate, rendering them useless. For example, most organic solvents will dissolve latex rubber.
- 2. Permeation rate The rate at which a specific chemical diffuses through glove material.
- 3. Breakthrough time The amount of time required for a given chemical to penetrate through a glove.

Type of gloves

Type of Gloves



Glove compatibility chart

Glove Selction Guide

Properties	Latex	Nitrile	Vinyl
Barrier protection against viral transmition	***	**	*
Tear resistance	**	**	*
Puncture resistance	*	**	*
Tensile strength and elasticity	***	**	*
Protein content	Present	Not Present	Not Present
Comfort and finger dexterity to reduce hand fatigue	***	**	*
Tactile sensitivity for better feel	***	**	*
Resistance to oil and solvents	*	***	**
Resistance to chemicals	*	***	*
Food contact safety	***	***	***
Biodegradable and environmentally friendly	***	*	*
Price	**	*	***

Indicator: Fair * Good ** Excellent ***

Chemical Resistance Chart

This Chemical Resistance Chart is intended to provide general information about the reactions of different glove materials to the chemicals listed. SAS Safety gloves have not been individually tested against these chemicals. Variability in glove thickness, chemical concentration, temperature, and length of exposure to chemicals will affect the performance.

Key: P=Poor, F=Fair, G=Good, E=Excellent, NR=Not Recommended

Chemical	Neoprene	Nitrile	Latex	PVC	Chemical	Neoprene	Nitrile	Latex	PVC
cetaldelryde		-		- NA	Kerosene		A 41 17 4		F.
Acetic Acid		- 6	G ·		Lactic Acid		HEAT PERSON		
Acetone	0	1000	0	9675	Lauric Acid			G	
Cetonitrile	-	7475		100	Linoteic Acid	- 2		Total Street	- 10
Immoneum Hydroxide-30%				100	Linsond Oil				- 1
Arryle Acetate	800		9		Maleic Acid				- 11
Amyl Alcohol	7440	Ġ.		100	Methyl Acetate	- 0		- 16 - 1	- 100
Anglina		300	- 0		Methyl Alcohol				- 6
Animal Fats		_		- 4	Methylamine	- 0	1.6		- 1
lattery Acids			-0	NA NA	Methyl Bromide	800			NET
lenzaldehydo	1471	9619		-	Methylene Chloride	1411	300	MIII	2611
Jenzone .	100	- 1	NIT	MICH	Mathyl Callusoive	6	- 7		- +
lenzoly Chlorida	NH	5470	2	5600	Methyl Ethyl Ketona (MEK)		HIT.	6	PER
Julane	- 7				Methylisobutyl Ketone	9017			- NH
Julyl Acetala	1075			NO	Methyl Methacrylate	140			NIK.
lutyt Alcohol		_		- 6	Mineral Oil		-	- 20	_
lutyl Collusolve*				100	Mineral Spirits	- 4		98	- i
			_	- 6		-			
larbon Acid	100	100		-	Monoethanolamine				
Sarbon Disuffide	N/A	HIN	100	HO	Morpholine			- 0	- 1111
Jarbon Tetrachlorida		0	20	- 44	Munatic Acids		10	G NN	-0
laster Oil		6	E .	2616	Naptha V.M.& P.	i i		MIN	
silosote Acetate		- 6	- 0	2616	Nitric Acid «30%	The second second	P	TO S	44
Cellosole Solvent		- 6		MN	Natrile Acid 70%		NB	- 1	
hlorobenzene	100	100	94/5	MB	Nitrite Acid Red Furning	888	546	No.	-
hioroform	7	-	900	500	Nitrile Acid White Furning	600	- 60	$-v_{-}$	- 10
Chloronaphalons			5475	100	Nitrobenzene	100	500		1481
	NIR Link					101			_
hioroethene VG	885		HH	P	Nitromethane		F		
Bromic Acid			HIR	0	Netropropane	0	MPI		- 100
Hric Acid					Outyl Atcohol		100	0	- F.
Ottonsed Oil	16		- 45	0	Oleic Acid				- 1
resols	- 10	- 6		- 6	Paint Remover	- 6	- 6		-
Sutting Oil	- 1			10.	Fulmitic Acid		- 0	G	- 0
harlaharana		-	_	=	Pentachlorophenol				
Syclohexane Syclohexanol			=	-6	Pentane				_
Tyclerikanior			_	- 4					-
Shutyl Phthalate		4			Perchloric Acid 60%				
Siethylamie	1,000	F	1800	NR	Potassium Hydroxide «50%»		4	Marrie, poss	
N-Isobutyl Ketone				100	Printing Ink			G G	
Simethyl Formamida (DMF)	- a	1671		NA	Propyl Acetate Propyl Alcohol	- 44			1671
Dirnethyl Sulfoxide (DMSO)			64 10	m	Propyl Alcohol	100 100	100	The second second	-
Scotyl Phthalate (DOP)	- 4	- 6	100 Per 100	MB	Perchloroethylene	1431	- 4	MH	PATE 1
noxane	3200	1901	100	NB	Phenol		HIT	- 6	- 6
Thyl Apotate		6481		100	Phosphoric Acid*		-	- 2	- 4
		100		2000	Picric Acid		200		
thyl Alcohol				nn_	Piche Adid	-	- 140	6	- 6
Hylana Dichlorida	1971	10.51		10.04	Propyliene Oxide	N/II			- MAL
Hylene Glycol	The second second	THE RESERVE	No. of Lot, Lot, Lot, Lot, Lot, Lot, Lot, Lot,		Rubber Solvent	- 0	March March	MIN	HILL
thyl Ether			2011	971	Sodium Hydroxide <50%		CONTRACT OF STREET		-0
thylene Trichtoride	-			MIN	Stoddard Selvent				PHT.
ormaldehyde	- 2				Styrene*	N/I	5675	800	MIN
pennis Asid		\rightarrow	The Part of the Pa	100	Sulfurio Acid 95%	-	- 4	NO.	Male
reon			100	NR.	Tannic Acid				-
urbiral	- 8	100			Tetrahydrofuran (THF)	NA	- 405	NO	HE
		-	-	100	Totueno		- 0		
asellino			1111		Totalino		100	HIT	1611
lykjerine					Toluene Di-Isocyanate (TDI)	NIT		100	- 14
fexane	-		9111	MIL	Trichlorethylene (TCF)		E STATE	ALC: N	NY
lydrautic Fluid Petro, Basud	-			0	Triricrestyl Phosophate (TCP)		Name of Street	- 6	- 1
tydraulic Fluid Easter Based			-	- 11	Triethanolamine 85% (TEA)			0.0	- 1
lyttramma 65%					Tunn Oil	1	The state of the s	3675	-
tydrochloric Acad*	- 1				Eurbine Oil		- 4		- F
					Turpentine	- 6		- 10	-
tydrofluoric Acid	- 9	وكالكا					1		-i
fydrogen Peroxide fydrogunene sobudyl Alcehol			الساليسية		Vegetable Oil			- 10	
fydroquinene					Xylone		.0	100	- 111
sobubil Alcohol	165		THE RESERVE	F12					
so-Octane			- 1000	P		100			
sepropyl Alcohol*									

* Warning: Protective gloves and other protective apparel selection must be based on the user's assessment of the workplace hazards. Glove and Apparel materials do not provide unlimited protection against all chemicals. It is the user's responsibility to determine before use that the Glove and Apparel will resist permeation and degradation by the chemicals (including chemical mixtures) in the environment of intended use. Failure by the user to select the correct protective gloves can result in injury, sickness, or death.





Types of Gloves cont.

Norfoil laminate resists permeation and breakthrough by an array of toxic/hazardous chemicals. Resistant to a wide range of solvents, acids, and bases



Butyl provides the highest permeation resistance to gas or water vapors; frequently used for ketones (M.E.K., Acetone) and esters (Amyl Acetate, Ethyl Acetate).



Types of Gloves cont.

Viton is made specifically for handling chlorinated and aromatic solvents, exhibit a high degree of impermeability to these solvents and can be used in or around water and water-based solutions. Viton also has superior resistance to PCBs



Nitrile provides protection against a wide variety of solvents, harsh chemicals, fats and petroleum products and also provides excellent resistance to cuts, snags, punctures and abrasions.



Ways to protect your skin

- Choose the right PPE for the specific agent you are working with.
- Cover any portion of the skin that is likely to be exposed
- Examples include lab coats, aprons, sleeves, coveralls, head coverings, or protective footwear.

Lab coat requirements

- Lab coats made of polyester-cotton blends (no less than 35% cotton) are acceptable in labs where no open flames are present.
- Lab coats must be made of 100% cotton or flame resistant material in labs where open flames are used (such as alcohol burners).
- Labs that store large quantities (>10gallons) of flammable liquids outside a flammable storage cabinet must use lab coats made of 100% Cotton treated with flame retardant material.
- Lab coats of flame resistant (FR) material are required in labs where pyrophoric materials are handled.

Select lab coat/apron using the following recommendations:

- Length At least knee length or longer is recommended for most effective coverage.
- Wristband It is recommended that a lab coat with a fitted wristband/cuff be used to reduce the potential for splashes up the arm and fire hazards.
- **Top button** It is best to use a lab coat that provides for a high top button at the neck to provide most effective protection.
- Fire resistant Use only those constructed of a flame resistant material

Material/Source	Features	Pros	Cons
80% Polyester / 20% Cotton, 65/35, and 40/60 are common blends.	Liquid Resistance Splash resistant. No specific chemical resistance. Better protection against corrosive material than cotton. Flame Resistance No	Appropriate for use in clinical settings and research laboratories where biological material is manipulated.	Polyester blends burn readily when ignited, and are not appropriate for use with flammable liquids, pyrophoric materials, or near open flame.
	Liquid Resistance Not splash resistant. No specific chemical resistance. Cotton lab coats provide better protection from solvent contamination than corrosive contamination. Flame Resistance No	Appropriate for use in clinical settings and research laboratories where there is light flammable liquid or open flame use.	Cotton lab coats should be supplemented with a chemical splash apron when corrosive material is handled.
	Liquid Resistance Not splash resistant. No specific chemical resistance. Flame Resistance Yes Flame-resistant (FR) fabrics and garments are intended to resist ignition, prevent the spread of flames	laboratories where substantial fire risk exists from flammable material handling or open flame use.	More costly than a traditional 100% cotton lab coat.
	Liquid Resistance Flame Resistance Yes When in contact with direct flame or extreme heat, fibers in the protective clothing enlarge, enabling greater distance between the user's skin and heat source. Comfort Breathable, but slightly bulkier than polyester blend or 100% cotton materials.	Appropriate for use in research laboratories where there is extreme fire danger from open flame, electrical arc flash, and pyrophoric material.	Expensive.
DuPont Tyvek lab coats	Liquid Resistance Barrier to particles, biological fluids, and chemicals. Flame Resistance Not flame retardant and melts at 135° C (275° F)	Appropriate for use in clinical settings and research laboratories where biological material is manipulated Excellent protection against microscopic airborne particles	Inappropriate for use in environments with a significant fire danger,

Protection against inhalation hazard

The use of a respirator may be necessary to protect against vapors and chemical particulates.

The keys to effective respirator use are proper fit and the selection of the appropriate cartridge

Anyone using a respirator (including N95 dust masks) must first receive a medical evaluation, approval, and training

Chemical Cartridge Color Coding All manufacturers use the same color coding for gas/vapor protection		
Color	Туре	
White	Acid Gas	
	Organic Vapors	
Green	Ammonia Gas	
Yellow	Acid Gas & Organic Vapor	
Olive	Mulit-gas (protects against numerous gases and vapors)	
Magenta	Particulate Filter Cartridge (HEPA) (Also called P100)	

Hearing Protection



Examples of Hearing Protectors

Earmuffs

can reduce noise by as much as 15 to 30 decibels

Earplugs

foam ear plugs to fit ear canals of different sizes.

Canal Caps

provide less protection than ear muffs or plugs,







Contact OEHS for a noise level evaluation if you suspect of noise pollution

Foot Protection



Wear shoes that cover your toes. No sandals and flip flops in the lab

PPE Maintenance

- Always inspect PPE for damage (tears, holes, worn elastic, etc.) and contamination prior to use.
- If an item cannot be properly cleaned or becomes damaged it should be discarded.
 When in doubt, throw it out.
- Reusable PPE should be immediately cleaned after each use with the appropriate cleanser (usually soap and water

Proper use of PPE

- Disposable items should only be used once and replaced when contaminated.
- Always assume PPE is contaminated: it is worn to protect against hazardous substances.
- Remove PPE prior to exiting the lab to help prevent the spread of contamination.
- Be sure you know the proper methods for putting on, taking off and fit-checking any PPE worn.

Storage of PPE

- Separate from chemicals and other contaminants.
- Store away from sources of heat
- Do not store under heavy objects
- Be aware that some equipment may have a limited shelf life.

Limitations of PPE

- No single PPE will protect you from all hazards.
- Consider permeation rates, compatibility and degradation for the chemicals you are working with.
- PPE may limit your dexterity, vision, grip strength, or comfort. Plan your work accordingly

Summary

- Conduct a risk analysis for the workplace for likely hazards at the work place
- Use engineering and work practice controls to eliminate or reduce hazards before using PPE
- Educate the everyone about the importance of the PPE program and how and when to use PPE
- Train everyone how to use and care for their PPE and how to recognize deterioration and failure
- Employees are to required to wear the PPEs as recommended by the supervisor

Acknowledgement of Training

 Click here to acknowledge receipt training in PPE for Labs training

References

- OSHA Office of Training and Education
- EH&S, University of California, Los Angeles